



Photo 11: Excavation of area showed directional fire patterns but identified no competent heat of ignition.




Photo 12: The first base cabinet contained a PVC drain for the sink. The remains of this PVC pipe provided additional directional fire spread patterns.



Photo 13: Openings in base cabinet (removed) and combustible wall exposed the polyethylene vapor barrier, PVC drain pipe and access to the “balloon construction-like” wood framing.




Photo 14: After the sink cabinet was removed, initial directional fire spread indicators were present on the PVC drain pipe and wood members of the wall.



Photo 15: Another view of the indicators of initial fire spread.